



NSS Exposed for 1,200 Hours



G235
Overbend (Tool Defects)




G235
"Flat" w.Perf.



G235
"Flat" Field



HDG G40 + CG-AG
Overbend (Tool Defects)



HDG G40 + CG-AG
Expanded Sidewall - Edge Test



HDG G40 + CG-AG
"Flat" Field